


# 7. Level 2 Repair

### 7-1. Components on the Rear Case





## 7-2. Pre-requisite






### 7-3. Parts which must be changed after repair

Assy\_OCTA\_Tape [GH81-13024A] Assy\_OCTA\_CU\_SHEET [GH81-13050A] **Touck Key TOP TAPE** [GH81-13060A]



### 7-4. Disassembly



(Must remove the 6th hook.)



5 1) Disassemble the PBA Assy.



**※** Caution

1) Becareful not to Damage.



## 7-5. assembly

1 1) Attach Bracket Assy



1) Attach the Bracket Assy



- 1) Be care of tilting.

- Caution
- 1) Be care of tilting.

1) Assemble PBA to the Bracket



4 1) Assemble Rear



- \* Caution
- 1) Be careful not to Damage.

- % Caution
- 1) Be careful not to Damage.
- 2) Be careful not to Damage SPK FPCB



Torque: 1.1 Kgf/cm²

Screw: 1.4 \* 3.5 (6001-003227)

★ Caution

1) Must Check Home key assembled.



